


Light'N Wire Productions

Basic Lightwire Connection

Lightwire


Step 1 - Strip wire





Lead wire




Step 2 - Apply copper tape




Step 3 - Solder wrap wires to copper tape



Step 4 - Remove phosphor



Step 5 - Solder short lead to center wire



Step 6 - Solder long lead to copper tape

